



AMERICAN INTERNATIONAL INDUSTRIES

Safety Data Sheet

GIGI All Purpose Golden Honee Hard Wax Beads

SECTION 1: Identification of the substance/mixture and of the company/undertaking

Product identifier

Product name GIGI All Purpose Golden Honee Hard Wax Beads

Product number 67985, 0318

Other means of identification

Uses: Personal Beauty Care

Details of the supplier of the safety data sheet

Name American International Industries
Address 2220 Gaspar Ave
Los Angeles, CA 90040
USA

Telephone 323-728-2999

Emergency telephone number

Chem-Tel: 1(800) 255-3924

SECTION 2: Hazards identification

Classification of the substance or mixture

Classification according to Regulation (EC) No 1272/2008 (CLP) and OSHA Hazardous Communication Standard 29 CFR §1910.1200.

- Sensitization, skin (chapter 3.4), Cat. 1, H317

Label elements

Labelling according to Regulation (EC) No 1272/2008 [CLP] and OSHA Hazardous Communication Standard 29 CFR §1910.1200.

Hazard pictograms**Signal word**

Warning

Hazard statement(s)

H317 May cause an allergic skin reaction

Safety Data Sheet

GIGI All Purpose Golden Honee Hard Wax Beads

Precautionary statement(s)

P261

Avoid breathing dust/fume/gas/mist/vapours/spray.

P271

Use only outdoors or in a well-ventilated area.

P272

Contaminated work clothing should not be allowed out of the workplace.

P280

Wear protective gloves/protective clothing/eye protection/face protection.

P333+P313

If skin irritation or a rash occurs: Get medical advice/attention.

SECTION 3: Composition/information on ingredients

Mixtures

Components

Component	Concentration
Rosin (CAS no: 8050-09-7)	30 – 50%
CLASSIFICATION: Sensitization, skin (chapter 3.4), Cat. 1 HAZARDS: H317: may cause an allergic skin reaction.	
Non Hazardous	40 – 60%
CLASSIFICATION: Not classified. HAZARDS: Non hazardous.	

SECTION 4: First aid measures

Description of first aid measures

General notes

Consult a physician. Show this safety data sheet to the doctor in attendance.

Following inhalation

Do NOT induce vomiting. Never give anything by mouth to an unconscious person. Rinse mouth with water. Consult a physician.

Following skin contact

Wash off with soap and plenty of water.

Following eye contact

Flush eyes with water as a precaution.

SECTION 5: Firefighting measures

Extinguishing media

Use extinguishing media appropriate for surrounding fire. Dry chemical powder, Alcohol-resistant foam, Carbon dioxide (CO₂).

Advice for firefighters

Wear self-contained breathing apparatus for firefighting if necessary.

SECTION 6: Accidental release measures

Personal precautions, protective equipment and emergency procedures

Ensure adequate ventilation. Use personal protective equipment. For personal protection see section 8.

Environmental precautions

Small or household quantities may be disposed in sewer or other liquid waste system. For larger quantities check with your local water treatment plant.

SECTION 7: Handling and storage

Precautions for safe handling

Safety Data Sheet

GIGI All Purpose Golden Honee Hard Wax Beads

Avoid exposure to skin and eye. Good standards of safe working practice and industrial hygiene should be observed.

Conditions for safe storage, including any incompatibilities

Original packaging units tightly closed at room temperature (below 25C)

SECTION 8: Exposure controls/personal protection

Control parameters

None Known

Exposure controls

Appropriate engineering controls

General industrial hygiene practice.

Personal protection equipment

Eye and face protection

Eye/Face Protection: None required with normal household use. Industrial Setting: For splash protection, use chemical goggles. Eye wash fountain is recommended.

Skin protection

Distribution, Workplace and Household Settings: No special protective equipment required. Product Manufacturing Plant (needed at Product-Producing Plant ONLY): Wear suitable protective clothing.

SECTION 9: Physical and chemical properties

Information on basic physical and chemical properties

Appearance	Gold coloured solid
Odour	Characteristic
Odour threshold	No data
pH	Not applicable
Melting point / freezing point	No data
Initial boiling point and boiling range	>250
Flash point	>250
Evaporation rate	No data
Flammability (solid, gas)	Non flammable
Upper/lower flammability limits	No data
VOC	Not applicable
Vapour pressure	No data
Vapour density	No data
Relative density	No data
Solubility	Insoluble
Partition coefficient: n-octanol/water	No data
Auto-ignition temperature	No data
Decomposition temperature	No data
Viscosity	No data
Explosive properties	No data
Oxidizing properties	No data
Viscosity (RV/T)	No data
Specific Gravity	~0.98

SECTION 10: Stability and reactivity

Safety Data Sheet

GIGI All Purpose Golden Honee Hard Wax Beads

Reactivity

None under normal use conditions.

Chemical stability

Stable under recommended storage conditions.

Possibility of hazardous reactions

None under normal use conditions.

SECTION 11: Toxicological information

Information on toxicological effects

Acute toxicity

No data available

Skin corrosion/irritation

No data available

Serious eye damage/irritation

No data available

Respiratory or skin sensitization

No data available

Carcinogenicity

This product is or contains a component that is not classifiable as to its carcinogenicity based on its IARC, ACGIH, NTP, or EPA classification.

Reproductive toxicity

No data available

STOT-single exposure

No data available

STOT-repeated exposure

No data available

Aspiration hazard

No data available

SECTION 12: Ecological information

Toxicity

No known hazards

SECTION 13: Disposal considerations

Waste treatment methods

Disposal of the product

Collect all waste in suitable and labeled containers and dispose according to local legislation. Can be recycled.

SECTION 14: Transport information

Safety Data Sheet

GIGI All Purpose Golden Honee Hard Wax Beads

UN DOT (US)

Not regulated

IMDG

Not regulated

IATA

Not regulated

SECTION 15: Regulatory information

Safety, health and environmental regulations/legislation specific for the substance or mixture

Toxic Substances Control Act (TSCA) Inventory

The components of this product are listed on the TSCA Inventory as appropriate.

SARA 311/312 Hazards

No SARA hazards.

Massachusetts Right To Know Components

No components are subject to the Massachusetts Right to Know Act.

New Jersey Right To Know Components

No components are subject to the New Jersey Right to Know Act.

Pennsylvania Right To Know Components

No components are subject to the Pennsylvania Right To Know Act.

WHMIS (Canada)

Not subject to WHMIS classification.

SECTION 16: Other information

Further information/disclaimer

This Safety Data Sheet is offered pursuant to OSHA's Hazard Communication Standard, 29 CFR § 1910.1200 and GHS. To the best of A.I.I.'s knowledge, the information contained herein is reliable and accurate as of this date; however, accuracy, suitability or completeness is not guaranteed and no warranties of any type, either expressed or implied, are provided. The information contained herein relates only to the specific product(s). If this product(s) is combined with other materials, all component properties must be considered. Data may be changed from time to time. Be sure to consult the latest edition.